

4M Change Information Notice

1.1 Information Notice Overview

Nesscap IN Number	IN-PJ-75-753-17003
Date of Publication	Sept. 13, 2017
Type of Change	Change in Rubber Bung

1.2 Affected Products

EDLC - Small Cells	XP 2.7V-3F	ESHSR-0003C0-002R7UC
	XP 2.7V-6F	ESHSR-0006C0-002R7UC

1.3 Reason of Change

The rubber bung used for the affected products was redesigned to improve overall urethane potting process and quality.

1.4 Description of Change

Potting pocket was created around each terminal hole to ensure that the potting solution spreads and covers only the required area in accordance with the Nesscap potting standard. Please refer to the images in Section 1.8.

1.5 Customer Impact & Recommended Actions

This change has no impact on the product specification, so no actions are needed from the customer side.


1.6 Customer Benefit

N/A

1.7 Identification of Post Change Material

N/A

1.8 Attachments



1.9 Migration Plan

Planned Date of Change	The change was implemented for all XP 3F and XP 6F products that have been shipped out from the Nesscap factory since Jun. 27, 2017.
------------------------	--

1.10 Contact Information

Contact by Mail	Attn: Nesscap Marketing Team Nesscap Co., Ltd. (446-901) 17, DongtanGiheung-ro 681beon-gil, Giheung-gu, Yoingin-si, Gyeonggi-do, Republic of Korea
Contact by Email	marketing@nesscap.com
Contact by Phone	+82-31-289-0722